Errata to the January 1, 2002 Georgia Amendments to the 2000 CABO 1 and 2 Family Dwelling Code/ International Residential Code

Update your copy of the January 1, 2002 Georgia Amendments to the CABO 1 and 2 Family Dwelling Code/International Residential Code, 2000 Edition, by making the following correction(s):

CHAPTER 3 BUILDING PLANNING

SECTION R317 SMOKE ALARMS

R317.1 Smoke detectors required.

Change next to last sentence to: All detectors shall be interconnected such that the actuation of one alarm will actuate all the alarms in the individual unit and shall provide an alarm which is audible in all sleeping areas.

CHAPTER 5 FLOORS

SECTION R502 WOOD FLOOR FRAMING

R502.2.1 Decks. Change R505.2.1.1, R505.2.1.2 to R502.2.1.1 and R502.2.1.2

CHAPTER 24 FUEL GAS

SECTION G 2409 (308) CLEARANCE REDUCTION

G2409 (308) CLEARANCE REDUCTION

Change SECTION G2409 (308) CLEARANCE REDUCTION to SECTION G2408 (305) INSTALLATION

G2409.2 Reduction table. Change G2409.2 Reduction table to G2408.2 (305.2) Elevation of ignition source.

End of Errata.

GA Standard Building Code (International Building Code) Amendments 2002 Errata